

## Service Bulletin

17-049

March 28, 2019 Version 3

## Brake Judder (2013-18 RDX)

This bulletin is replaced by S/B 19-009, Front Brake Noise and/or Front Brake Judder

This bulletin replaces S/B 16-002, Front Brake Noise and/or Front Brake Judder (2013-16 RDX)

This bulletin is replaced by S/B 19-009, Front Brake Noise and/or Front Brake Judder. If you completed work pursuant to S/B 17-049 on or before March 28, 2019, make sure to use the warranty claim information provided below.

## WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
4101F5	Replace the front brake discs.	0.5 hr	03214	04201	B17049A	45022-TX4-A01
А	Replace the front brake pads.	0.2 hr				
410820	Refinish the front brake discs, and replace the front brake pads.	0.9 hr	03214	04201	B17049B	45022-TX4-A01

Skill Level: Repair Technician

**END** 

**CLIENT INFORMATION:** The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.