

## Seat belt does not roll up correctly

Topic number	LI91.40-N-051128
Version	2
Design group	91.40 Seat belts, emergency tensioning retractors
Date	06-21-2017
Validity	Models 901 - 906
Reason for change	Distribution revised
Reason for block	

### Complaint:

Seat belt does not roll up completely

### Cause:

Dirt deposits on the seat belt guide bracket due to a soiled seat belt

Attachments	
File	Description
photo1.jpg	Dirt on seat belt guide

### Remedy:

Cleaning of the belt guide.

Clean the belt guide using MB Plastic Cleaner.

Clean the seat belts using MB Car Wash mixed with water or MB Upholstery Foam Cleaner and a microfiber cloth. Do not treat the belt with other cleaning agents. Clean using MB Car Wash mixed with water, MB Upholstery Foam Cleaner or clean, lukewarm water and soap. Do not dry at temperatures above 80 °C or in direct sunlight.

### Important:

If these instructions are ignored, proper functioning of the seat belts may be impaired.

Symptoms
Body / Safety system / Seat belt / Seat belt / Belt strap rolls up poorly

Parts						
Part number	ES1	ES2	Designation	Quantity	Note	EPC
A 000 986 51 71			MB Plastic Cleaner	1	Clean the seat belt guide only, not the seat belt itself	X
A 001 986 41 71			Car Wash	1		X
A 001 986 25 71			Textile cleaner	1		X

Operation numbers/damage codes

# XENTRY TIPS

Op. no.	Operation text	Time	Damage code	Note
			91051 H2	Seat belt, front seat The listed damage code is not to be considered as an acceptance of costs. The general guidelines in the Warranty Manual apply.
			91158 H2	Seat belt, front passenger seat The listed damage code is not to be considered as an acceptance of costs. The general guidelines in the Warranty Manual apply.
			93091 H2	Seat belt, multiseat bench The listed damage code is not to be considered as an acceptance of costs. The general guidelines in the Warranty Manual apply.

Validity		
Vehicle	Engine	Transmission
Sprinter I	*	*
Sprinter II	*	*
Sprinter III	*	*

Attachments

# XENTRY TIPS

---

photo1.jpg:

