



Engine	Part	Part Number	Quantity
	Oil Filter 06A-115-561-B		1
2.0L CBPA	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	4.0L (4.2qt)
	Drain Plug Gasket	N-91086801	1
	Air Filter	1F0-129-620	1

Engine	Part	Part Number	Quantity
	Oil Filter	06L-115-562	1
1.8L Turbo: CPKA, CPRA	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	5.5L (5.7qt)
	Drain Plug Gasket	N-0138157	1
	Air Filter	5C0-129-620	1

Engine	Part	Part Number	Quantity	
	Oil Filter 06L-115-562		1	
2.0L Turbo GLI: CPLA, CPPA	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30	N/A	5.5L (5.8qt)	
	Drain Plug Gasket	N-0138157	1	
	Air Filter	5C0-129-620	1	

Engine	Part	Part Number	Quantity
	Oil Filter	04E-115-561-H	1
4 41 11 behinder ONII A	VW 502 00 Use synthetic oil SAE 5W-40, SAE-5W-30		4.0L (4.2qt)
1.4L Hybrid: CNLA	Drain Plug	N 90288901	1
	+ Gasket	N 0138157	-
	Air Filter	04E-129-620	1
	Fuel Filter (Every 20K miles)	1K0201051K	1





Engine	Part	Part Number	Quantity	
	Oil Filter	03N-115-562	1	
2.0L TDI: CVCA	VW 507 00 Use synthetic oil SAE 5W-30	N/A	5.5L (5.8qt)	
(California Emissions	Drain Plug Gasket	N-90813202	1	
States only)	Air Filter	1K0-129-620-D w/PR-0Y2	1	
	Fuel Filter (20K Only)	5Q0127177	1	

Engine	Part	Part Number	Quantity
	Oil Filter	03N-115-562	1
	VW 507 00 Use synthetic oil N/A SAE 5W-30		5.5L (5.8qt)
2.0L TDI: CVCA	Drain Plug Gasket	N-90813202	1
	Air Filter	1K0-129-620-L w/PR-0Y3	1
	Fuel Filter (20K Only)	5Q0127177	1

Miscellaneous	Part	Part Number	Quantity
	Pollen Filter (20K Only)	1K0-819-644-B w/ PR-9AK	1
	Pollen Filter (20K Only)		1
	Driver's Wiper Blade (Left)	5C7-955-425-B	1
Miscellaneous	Passenger's Wiper Blade (Right)	5C7-955-426-B	1
	Battery	000-915-105-DE-DSP (61AH/330A)	1
	Battery	000-915-105-DG-DSP (72AH/380A)	1
	Battery	000-915-105-CC-DSP (68AH/380A)	1





Resetting the oil change service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the oil change service reminder can be reset as follows:

Ve	hicles with Premium display:
1.	Switch off the ignition.
2.	Press and hold the 0.0/\$ET button in the instrument cluster.
3.	Switch on the ignition.
4.	Release the 0.0/SET button.
5.	A confirmation message appears in the display. Confirm request with the OK/RESET in the windshield wiper lever or the OK button on the multi-function steering wheel.
Ve	hicles with Basic display:
1.	Switch off the ignition.
2.	Push the 0.0/SET button in the instrument cluster and hold down.
3.	Switch on the ignition.
4.	Release the 0.0/\$ET button and push the 🔁 🕘 button in the instrument cluster within about 20 seconds.

Resetting the inspection service reminder

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the inspection service reminder can be reset as follows:

Vehicles with Premium display:		
1.	Switch off the ignition.	
2.	Switch on the emergency flashers.	

© 2017 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.





Vehicles with Premium display: 3. Press and hold the 0.0/SET button in the instrument cluster. 4. Switch on the ignition. 5. Release the **0.0/SET** button. 6. A confirmation message appears in the display. Confirm request with the **OK/RESET** in the windshield wiper lever or the **OK** button on the multi-function steering wheel. 7. Switch off the emergency flashers. Vehicles with Basic display: 1. Switch off the ignition. 2. Switch on the emergency flashers. 3. Push the 0.0/SET button in the instrument cluster and hold down. 4. Switch on the ignition. 5. Release the **0.0/SET** button and push the \(\frac{1}{12} \) button in the instrument cluster within about 20 seconds.

6. Switch off the emergency flashers.

Do **not** reset the service reminder between service intervals; otherwise incorrect information will be displayed.

The service reminder disappears after a few seconds or after the **OK/RESET** button on the windshield wiper lever or the **OK** button on the multi-function steering wheel has been pushed.

© 2017 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

Jetta/GLI Page 1 of 2

Copyright VW AG

Repair manual ElsaPro Job no.: 648392

DMS Repair Order number: undefined

VIN: Model year: 2015

Model code: 163 Model description: Jetta 4-tuerig LI

Engine code: CBPA Transmission code: MAM

License plate: Final drive code:

User name: **Dean** Service advisor - name:

Jetta/GLI



Caution

All quantities are approximate. Always refer to the Repair Manual and/or the Maintenance Procedures for correct filling instructions.

Refer to Technical Bulletin 2012855 for engine oils meeting the required VW oil specifications.

Part numbers are for reference only. Always check with your parts department for the latest information.

Component/System		Capacity	Part Number/Specification
1.8 L CPKA/CPRA			
	Oil and Filter Change	5.5 L (5.7 qt.)	VW 502 00
	Coolant	8.0L (8.5 qt.)	G 13 (TL-VW 774 J)
2.0 L TDI Engine CVCA			
	Oil and Filter Change	5.5 L (5.8 qt.)	VW 507 00
	Coolant	8.0 L (8.5 qt.)	G 13 (TL-VW 774 J)
2.0L CBPA			
	Oil and Filter Change	4.0 L (4.2 qt.)	VW 502 00
	Coolant	5.0 L (5.3 qt.)	G 13 (TL-VW 774 J)
2.0L CPLA/CPPA	·		
	Oil and Filter Change	5.5 L (5.8 qt.)	VW 502 00

Jetta/GLI Page 2 of 2

	Coolant	8.0 L (8.5 qt.)	G 13 (TL-VW 774 J)
5 Speed Manual Transmission 0A4			
	Initial Fill	1.9 L (2.0 qt.)	G 052 512 A2
5 Speed Manual Transmission 0AF	Initial Fill	2.0 L (2.1 qt.)	G 070 726 A2
6 Speed Manual Transmission 02Q			
	Initial Fill	2.3 L (2.4 qt.)	G 052 171 A2
6 Speed Automatic Transmission 09G			
	Initial Fill - Gen 1	7.0 L (7.4 qt.)	G 055 025 A2
	Initial Fill - Gen 2	6.1 L (6.4 qt.)	G 055 540 A2
6 Speed Direct Shift Gearbox 02E			
	Initial Fill	7.2 L (7.6 qt.)	G 052 182 A2
	Refill	5.2 L (5.5 qt.)	0 002 102742
	Mechatronic Only	3-4 L (3.1-4.2 qt.)	
AdBlue® Tank			
	_	14.4 L (3.8	G 052 910 A2 or
		gal.)	GUS 052 910 A3
A/C System			
	Refrigerant, Gasoline Engines	525 ± 25 g (18.5 ± 0.9 oz.)	See ETKA
	Refrigerant, TDI Engines	600 ± 25 g (19.2 ± 0.8 oz.)	See ETKA
	PAG Oil	110 ± 10 cc (3.7 ± 0.3 fl. oz.)	G 052 200 A2
Window/Headlamp Washer System			
	-	3.0 - 4.0 L (3.1 - 4.2 qt.)	G 052 164*