



Technical Tip

Topic	57-16-02TT – Door Lock Horn Chirp Operation
Market area	United States 444 Volkswagen of America, Inc. (6444)
Brand	Volkswagen
Date	March 15, 2019

Condition

ATTENTION:

THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.

TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.

Door Lock Horn Chirp Inoperative

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Jetta, Golf, GTI, Golf Sportwagen, Golf R, Tiguan, Passat, Beetle, Beetle Convertible	2016-2019	All	All	All	All

Technical Background

NA.

Service

The horn confirmation requires two rapid presses of the lock button on the key fob to sound. If the door lock confirmation sounds after pressing the lock button quickly, twice, the vehicle is performing as designed and no repairs are needed.

Additional Information

Revision History		
Revision Number	Released Date	Reason For Update
2046073/3	3/15/19	Update model year applicability.
2046073/2	6/16/17	Updated to latest standard.
2046073/1	11/25/16	Original publication.

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.