

Service Product Journal

TITLE:

Software Purchase Failed - General error occured - VDS / SPA / CMA cars

REF NO: 33554.1.0	ISSUING DEPARTMENT: Service Operations			REFERENCE BULLETINS:	
CATEGORY: Information Products	SUBCATEGORY: Wiring Diagrams			CAR MARKET: United States and Canada	
Service Personnel: Read and initial	SERVICE MANAGER	SERVICE WRITER	WARRANTY ADMINISTRATOR	ISSUE DATE: 2018-02-27 Page	STATUS DATE: 2018-03-01 1 of 2

[&]quot;Right first time in Time"

Attachment

File Name	File Size
Software Error.PNG	0.0259 MB
SoftwarePurchaseFix	2.258 MB

Background:

We have identified a corrupt software file which will cause purchase error in VIDA until it has been fixed centrally.

See "Software Error.PNG" for clarification about the error message that is shown in VIDA.

Temporary Solution:

- 1. Close down VIDA.
- 2. Copy the ZIP file to appropriate folder, AVOID copying it to the desktop if possible.
- 3. Unzip the file and run the bat file called "RUN THIS".
 - This will copy the attached VBF and XML file to the users ESWDL folder.
- 4. Open VIDA again and try to purchase.

Service Product Journal 33554.1.0



Final Solution:

The corrupt file will be removed and replaced Centrally with a working file. ETA - TBD

To view SPJ attachment see below. This SPJ has one attachment and one ZIP file.



Page 2 of 2 2018-03-01