

LATEST VEHICLE CONCERN FIXES



Check Engine Light with DTC P2170-11	18-19 MY Discovery Sport, RR Evoque, E PACE
<p>Customer Voice:</p> <ul style="list-style-type: none">- The Check Engine Lamp is on. <p>Technical Description:</p> <ul style="list-style-type: none">- DTC P2170-11 is stored in the PCM.- The active exhaust valve can be heard to operate during start. <p>Status:</p> <ul style="list-style-type: none">- We are investigating the role that ambient conditions play in setting this DTC.- SSM 74333 and SSM 74326 have been published which elaborate on the diagnostic steps to be performed for this DTC.- Updated PCM software has a revised DTC strategy which removes the restricted performance flag in order to reduce the impact to the customer.- Raise an EPQR for any vehicle exhibiting this condition and include results of all diagnostic steps performed. The vehicle can be released back to the customer.	

