

Technical Service Bulletin

SUBJECT:			No:	TSB-19-42A-004
WINDOW GLASS RUNCHANNEL & DOOR OPENING WEATHERSTRIP REMOVAL & INSTALLATION DATE: April 2019				
- SERVICE MANUAL REVISION			MODE	2016-19 Outlander
CIRCULATE TO:	[] GENERAL MANAGER	[X] PARTS MANAGER [X] TECHNICIAN		
[X] SERVICE ADVISOR	[X] SERVICE MANAGER	[X] WARRANTY PROCESSOR [] SALES MANAGER		

PURPOSE

This TSB updates the Body section of the affected Service Manual, to correct the window glass runchannel and door opening weatherstrip removal and installation procedure.

AFFECTED VEHICLES

2016 - 2019 Outlander

AFFECTED SERVICE MANUAL

• 2016 - 2019 Outlander Service Manual, Group 42-Body



Please make the indicated changes to the 2016 - 2019 Outlander Service Manual, Group 42-Body -> Door -> Specifications -> Adhesive.


ADHESIVE

M1423000500705


Item		Specification		
Door waterproof film		3M ATD Part No.8633 or equivalent		
Door opening front weatherstrip Incorrects		Double-sided tape: 3M SF6808 or commercially-available product [width; 6 mm (0.2 in), length (A); 60 mm (2.4 in), length (B); 80 mm (3.1 in), thickness; 0.8 mm (0.03 in)]		
		Specified primer: 3M K-540NT		
	<correct></correct>	Double-sided adhesive tape: 3M SF6812 or equivalent (J) thickness; 1.2 mm (0.05 in), width; 6 mm (0.2 in), length; 60 mm (2.4 in) (K) thickness; 1.2 mm (0.05 in), width; 6 mm (0.2 in), length; 60 mm (0.1 in)		
		length; 80 mm (3.1 in) (L) thickness; 1.2 mm (0.05 in), width; 4 mm (0.2 in),		

length; 80 mm (3.1 in)

Please make the indicated changes to the 2016 - 2019 Outlander Service Manual, Group 42-Body -> Door -> Window Glass Runchannel & Door Opening Weatherstrip -> Removal and Installation.



<Correct>



Double-sided tape: 3M SF6812 or equivalent

(J) thickness; 1.2 mm (0.05), width; 6 mm (0.2 in), length; 60 mm (2.4 in)

(K) thickness; 1.2 mm (0.05), width; 6 mm (0.2 in), length; 80 mm (3.1 in)

(L) thickness; 1.2 mm (0.05), width; 4 mm (0.2 in), length; 80 mm (3.1 in)

Specified primer: 3M K-540NT

Please make the indicated changes to the 2016 - 2019 Outlander Service Manual, Group 42-Body -> Door -> Installation Service Points -> Door Opening Front Weatherstrip Installation.

