

LATEST VEHICLE CONCERN FIXES



LED Headlamp Reflector

F-TYPE 18 MY Onwards

Customer Voice:

- The yellow reflector in the headlamp assembly is delaminating

Technical Description:

- The upper corner of the headlamp reflector has delaminated on F-TYPE vehicles fitted with LED headlamps

Status:

- Under investigation
- If the issue is noticed, do not replace the headlamp at this time. Please submit an EPQR with pictures of the reflector and the date code of the headlamp.

