


# LATEST VEHICLE CONCERN FIXES



PCV Diaphragm Torn	All models equipped with AJ126 or AJ133
<p><b>Customer Voice:</b></p> <ul style="list-style-type: none"><li>- The Check Engine Lamp is illuminated.</li></ul> <p><b>Technical Description:</b></p> <ul style="list-style-type: none"><li>- There is an unmetered air leak from the PCV valve diaphragm.</li></ul> <p><b>Status:</b></p> <ul style="list-style-type: none"><li>- A lower level repair kit has been developed and can be ordered through parts.</li><li>- Part number is LR133579 / C2D60163.</li><li>- Part will be delivered to the UK warehouses this week.</li><li>- Local sample parts stock has been exhausted, so please do not raise a TA to obtain parts.</li></ul>	 <p>The diagram illustrates the PCV valve assembly. It shows a side view of the valve (labeled 9K617B) and a top view of the valve housing (labeled 9K617A). A circular inset highlights the diaphragm components, with a callout box showing two diaphragm parts (labeled 13B802) and red lines indicating their location within the valve assembly.</p>

