

	GROUP Electrical	MODEL 2016-2019MY Optima (JFa), Sorento (UMa)
	NUMBER PS600	DATE May 2019
 		
SUBJECT: OUTSIDE MIRROR GLASS CONTROL INOPERATIVE		

This Pitstop provides information on the repair procedure for an inoperative mirror glass on the outside door mirrors for 2016-2019MY Optima (JFa) and Sorento (UMa) vehicles.

If the mirror glass cannot be adjusted, and the resulting diagnosis confirms the mirror actuator (A) is at fault, replace only the mirror actuator. DO NOT replace the complete mirror assembly. Below are the part numbers and Labor Op Code for only the actuator replacements, used on both 2016-2019MY Optima (JFa) and Sorento (UMa) vehicles.



2016-2019MY JFa and UMa Outside Door Mirror Actuators				
Model	Part Number (Non-Memory)	Part Number (w/ Memory)	Labor Op Code	Time
Optima (JFa)	87612 G2000 (Left)	87612 G2500 (Left)	87612R00 (One Side)	0.2 M/H
		87622 G2500 (Right)	87612R0B (Both Sides)	0.3 M/H
Sorento (UMa)	87622 G2000 (Right)	87622 2500 (Left & Right)	87602R00 (One Side)	0.3 M/H
			87602R0B (Both Sides)	0.5 M/H