



Preliminary Information

PIT5672 Air Suspension Dump Switch Operation

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 4500HD, 5500HD, 6500HD	2019	All	All	6.6L L5D	All

Involved Region or Country	North America
Additional Options (RPO)	GP8
Condition	There may be a concern with the operation of the rear suspension dump switch operation.
Cause	This concern is caused by internal operation of the switch.

Correction:

When the switch is activated the air will dump form the air bags lowering the vehicle, it should stay down until the vehicle is shifted into gear.

With the concern the vehicle will inflate the air suspension when the switch is released.

The correction for this is to replace the switches in the center stack.

Note: it is possible that the switches from parts may have the concern as well.

If found to have no stock Please get a SPAC case started.

Once the concern is resolved this PI will be deleted.

Version History

Version	1
Modified	04/12/2019 - Created on

