

LATEST VEHICLE CONCERN FIXES



Automatic Emergency Braking Not Available in Instrument Pack

18MY – 19MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport

Customer Voice:

- Automatic Emergency Braking not available.
- Forward alert not available.
- Emergency Lane Keeping not available.

Technical Description:

- Supplier manufacturing process error resulting in faulty hardware.
- DTC set in IPMA U3000-96 – Component Internal Failure.

Status:

- Supplier Permanent Corrective Action is completed on April 11th 2019.
- Parts stock is all clean.

