

Tech Tip T-TT-0550-19

June 19, 2019

Abnormal Noise from Rear Over Bumps

USA

Suspension

Rear Suspension

2019 MY RAV4 and RAV4 HV

APPLICABLE VEHICLES

2019	RAV4 HV	2019	RAV4

CONDITION

Abnormal noise from rear of vehicle when traveling over bumps.

RECOMMENDATIONS

Inspect rear coil springs for evidence of rubbing on lower arm. Coil spring may also appear misaligned or not seated correctly.

If the above condition is identified, STOP, DO NOT REPAIR, contact TAS for further instructions.

If it is a Sunday or holiday, continue with diagnosis and repair, save all parts and details (including pictures), and contact TAS at the next available opportunity.

LINK REFERENCES

This Tech Tip does not contain any link references

Expires on