

Subject: Engineering Information – Steering Wheel Off Center and/or Pulls to the Right

This PI has been revised to end the need for information from the field. Please discard PIE0484.

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|---------|-------------|------|------|----|---------|---------------|
| | | from | to | from | to | | |
| Chevrolet | Bolt EV | 2017 | 2019 | | | | |

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

| | |
|-----------------|--|
| Version | 2 |
| Modified | Released August 30, 2018 June 26, 2019 – Ended the need for further information from the field. |