

Page 1 of 1

Warranty Communication

Audi Warranty

Subject: Repair Validation and Clarification for Repair Group 19

Dealers: U.S., Puerto Rico

This communication is being issued to clarify the repair validation process for Repair Group 19 when there is a customer concern of leaking. Please note that the pressure test to validate the repair can be performed while the system is being filled. This is included in the main SRT, and no additional time is needed. Because the repair validation is performed by the pressure test, a test drive after the repair is not needed for validation and should not be claimed.

In addition, as with any claim, multiple repair lines should be reviewed to ensure there is no overlapping labor.

When performing repairs without a customer concern, always refer to the add-on policy in section *4.2 Add-on repairs*, the categorization of leaks explained in section *4.35 Leaks*, and the authorization requirements listed in *3.3.1 Required information on repair order* in the Audi Warranty Policies and Procedures manual. As a best practice, photo documentation may also be required to validate repairs.

Questions or concerns may be directed to Audi Warranty at 866.677.2834 or <u>AudiWarranty@audi.com</u>.

Number: AWC-19-04

Date: July 22, 2018

This document conveys general Warranty information.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies, and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise; nor may these materials be modified or reposted to other sites without the prior expressed written permission of the publisher.