

Latest Vehicle Concern Fixes



Check Engine Light illuminated, Restricted Performance Message on IPC	All Diesel Equipped Vehicles (17-19MY XE, XF, F-PACE & 18-19MY RR Velar AJ20D, 16-20MY RR & RR Sport, 17-20MY All New Discovery TDV6)
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Check Engine Light illuminated, Restricted Performance Message on IPC <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• P0087-22/21 setting for fuel rail pressure sensor <p><u>Status:</u></p> <ul style="list-style-type: none">• Under Investigation.• DTCs are for fuel rail pressure sensor.• If your retailer receives a vehicle with these DTC's stored, confirm with the customer that this is not a mis-fueling event. Once that information is obtained, please raise a TA. Engineering & Product Investigation are looking to visit a vehicle in an error state.• Parts will be called back for inspection for all vehicles that have had replacements for this DTC	

