

# Latest Vehicle Concern Fixes



## Broken / Cracked TPMS Valve Stems

17MY- Onwards RR Velar, Range Rover, RR Sport, RR Evoque, Discovery, Discovery Sport, E-PACE, F-PACE, I-PACE, F-TYPE, XJ, XE, and XF

### Customer Voice:

- The tire valve stem is broken or cracked.

### Technical Description:

- This damage may be caused by the use of an extended tire inflation chuck.

### Status:

- Damage due to the use of the extended tire inflation chuck should not be claimed under warranty.
- Warranty will be calling back TPMS sensors and valve stems for inspection.



E197021



E197833

