

Latest Vehicle Concern Fixes



No Audio Output or Loss of Audio	19MY – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• Customer states there is no audio output from the speakers on all sources <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• Topic is under investigation <p><u>Status:</u></p> <ul style="list-style-type: none">• Primarily reported on 19MY vehicles• Please raise a TA if a customer exhibits this concern, LTS may be able to recover this tool with the help of UK Engineering.	

