

Latest Vehicle Concern Fixes



Headlight Micro-cracking	15 – 17MY F-TYPE
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">• A Customer may report the headlights have small cracks on the lenses. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">• The micro-cracking is found on one and or both headlamp lenses on 15-17 MY F-TYPE. The issue is found concentrated above the headlamp beam on the clear part of the headlamp. <p><u>Status:</u></p> <ul style="list-style-type: none">• Parts are in transit to the PDC• Current parts stock will be quarantined and the new parts can be identified by a green dot.	 A close-up photograph of a black headlight lens. The lens is dark and glossy, with a prominent circular projector lens in the center. There are several fine, hair-like cracks visible on the surface of the lens, particularly concentrated in the upper portion above the main projector lens.

