



Service Bulletin

Bulletin No.: 19-NA-183

Date: August, 2019

INFORMATION

Subject: Mandatory VECI Label Replacement for (5W7) Performance Air Intake Kits

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|----------------------------|-------------|------|------|----|---------|---------------|
| | | from | to | from | to | | |
| Chevrolet | Silverado 1500 | 2014 | 2018 | | | All | All |
| | Silverado 1500 (New Model) | 2019 | 2019 | | | | |
| | Suburban | 2015 | 2019 | | | | |
| | Tahoe | 2015 | 2019 | | | | |
| GMC | Sierra 1500 | 2014 | 2018 | | | All | All |
| | Sierra 1500 (New Model) | 2019 | 2019 | | | | |
| | Yukon | 2015 | 2019 | | | | |

| | |
|-----------------------------------|------------------------------------|
| Involved Region or Country | North America, N.A. Export Regions |
|-----------------------------------|------------------------------------|

Bulletin Purpose


The Accessory Performance Air Intake Kits are a Dealer installed accessory for 2019 Full Size Trucks (GMC Sierra and Chevrolet Silverado) and 2019 Full Size SUVs (Chevrolet Tahoe, Chevrolet Suburban, GMC Yukon, and GMC Yukon XL). This Intake Kit replaces the production air cleaner assembly, which has the Vehicle Emissions Control Information (VECI) label attached to the Air Cleaner Lid. The VECI label is required by Federal Emissions Regulations and a missing label is a compliance issue. When installing the Performance Air Intake Kit, a replacement label (19354745) MUST BE ordered to meet emissions compliance.

1. Order service part number 19354745 for a replacement VECI label.


Note: This label is VIN specific and will require the full VIN number for the vehicle requiring the label.

To order the replacement VECI label go to **GlobalConnect » App Center » Electronic Parts Information (GM EPIC) » Emergency Order Entry**, input the full vehicle VIN in the comments. Select order type V for expedited delivery.

2. Dealer Piece Cost for the label will be billed to the BARS/Open Account monthly. Dealer Statement will include the Part Number Reference and Dealer Piece Cost.
3. The Dealer cost of the label (\$20.12 USD) and 0.2 hr allowable labor time is to be charged to labor OP code 0602798. The transaction type is ZREG.
4. Label will ship from the supplier in 1-2 business days.
5. Installation of Label - Clean the application surface so that there is no dust, oil, or other contaminants that will affect the label adhesion.
6. The label should be applied to the locations shown in the photos below to ensure that the label is visible in the engine compartment for emissions inspection purposes.



1. VECI Label placement for Trucks



5391157

1. VECI Label placement for SUVs

Effective Date

Follow this VECI Label Replacement procedure for all 2019 Full Size Truck and SUV that have the (5W7) Performance Air Intake (84561597, 84651598, 84533096).

Additional Information

Contact: tj.walsh@gm.com

Parts Information

| Causal Part | Description | Part Number | Qty |
|-------------|--|-------------|-----|
| | LABEL,VEH EMIS CONT INFO | 19354745 | 1 |
| | CLEANER KIT-AIR 2019 Next Generation Trucks | 84561597 | 1 |
| | CLEANER KIT-AIR 2014 - 2019 Full Size Truck | 84016022 | 1 |
| | | 84756329 | 1 |
| | | 84089441 | 1 |
| | 2015 - 2019 Full Size SUV | 84533096 | 1 |

Warranty Information

For vehicles repaired under warranty, use:

| Labor Operation | Description | Labor Time |
|--------------------------------|-------------------|------------|
| *0602798 | Label Replacement | 0.2 hr |
| *The transaction type is ZREG. | | |

| | |
|----------|--------------------------|
| Version | 1 |
| Modified | Released August 13, 2019 |

Additional Keywords: Air Intake, filter, Silverado, Sierra, Yukon, Tahoe, Suburban, Yukon XL, label, VECI label, emissions, performance, chevrolet performance

