

Latest Vehicle Concern Fixes



Heavier Than Expected Steering	2016 Onwards Range Rover & Range Rover Sport
<p>Customer Voice:</p> <ul style="list-style-type: none">• Customer states the steering is heavier than expected. <p>Technical Description:</p> <ul style="list-style-type: none">• The sleeve on I-shaft may have moved down on the I-shaft. <p>Status:</p> <ul style="list-style-type: none">• LTB01224 has been published to TOPIx to provide an inspection of the I-shaft and the new part number I-shaft should it require replacement.	 

