



CAMPAIGN FOR:  
**SCR Replacement US17-18 (13 Chassis)**

Description:

Pro-actively replacing SCR w/sensors for engineering inspection.

**Prior to beginning:**

Open an E-service case to Reliability attention Will Cheek for tracking purposes.

Instructions:

Replace Muffler (One Box) – Combined DOC-DPF-SCR Unit with Nox inlet, Nox outlet, and PM Sensors. **DO NOT REMOVE** Original Nox inlet, Nox outlet, and PM Sensors from one box. Return Unit with sensors untouched.

**Shipment Instructions:**

Package removed One Box the same way the new part arrived (on a pallet, strapped down). Leave Nox inlet, Nox outlet, and PM sensors in the unit. Update E-service case that the truck is complete and parts ready for return. We will arrange a dedicated pickup for the parts to be return.

UCHP SCC CODE: S7406

EXPIRATION DATE: 10/31/2019

UCHPLABOR CODES:

<b>Labor Code - Description - Hours</b>
<i>2589-03-02-43 Muf, Replace. Combined DOC-DPF-SCR - 1.7 hrs</i>

CAUSAL PARTNUMBER: 23159384

PARTS LIST: Parts are being provided at No Charge.

**NOTE:** Dealer may claim up to \$1700 compensation in "other costs" for handling parts.

ANY QUESTIONS ON WORK REQUIRED, CONTACT:

William Cheek [william.cheek@volvo.com](mailto:william.cheek@volvo.com)