

## Solution K10404781 Thursday, August 29, 2019 9:25:15 PM CEST

#### \*\* SOLUTION \*\*

Title	Volvo Chassis - Differential Lock Status Alarm And Icon; Differential Lock Alarm
	Tone Does Not Sound For Entire Duration Of Differential Lock Engagement
Volvo Models	
Volvo Model	VN, VNL, VNR, VNX, VAH, VHD
** SOLUTION **	
Cause	For certain Volvo vehicles, the differential lock alarm may not sound the entire time the differential lock is engaged. This issue can cause the driver to be confused about the status of the differential lock and may contribute to rear end failures. Currently the alarm will sound for 5 seconds and the instrument cluster pop-up message and icon can be missed.

#### **Solution**

### To remedy this issue please install new Instrument Cluster main software.

Refer to the chart and image below for the current and new configurations for the differential lock status alarm and icon.

GEN II Clusters			
Current	New		
• Engaged: (Popup + audible + icon)	• Engaged: (Popup + Audible + Icon)		
begins Audible is 5s popup dismisses after 30s	begins • Popup dismissed: (Continuous audible		
• Icon stays ON	+ Icon) persists		
Disengaged: Icon ceases	• Engaged > 30s after popup dismissal: (popup) returns (continuous audible +		
	Icon) persists		
	Disengaged: all (popup/Audible/Icon)		
	ceases		

Interwheel Lock is engaged

NA_Sister solutions	<u>K14810225</u>
Solution visibility	Dealer distribution

# Function(s)/component(s) affected

Function affected	MID 140 – IC04 / IC05, dashboard/information display, Drive Axle
Function Group	
Function Group	384 warning system , 387 warning/information analysis and display; embedded
	diagnostic software
Customer effect	
Main customer effect	calibration/programming/pairing/missing operation, locking/unlocking
Conditions	
Vehicle operating mode	when activating, during engagement
Administration	
Author	RU2761V
Dealer ID	RU2761V
Last modified by	A241298
Creation date	18-07-2019 14:07
Date of last update	14-08-2019 14:08
Status	Published