

 **HYUNDAI**
Technical Service Bulletin

GROUP INTERIOR	NUMBER 19-BD-004H
DATE AUGUST 2019	MODEL(S) Genesis (DH)


SUBJECT: SEAT BACKBOARD CLIP REPLACEMENT

Description: This bulletin describes the procedure to replace the seat backboard clip. Some vehicles may experience the seat backboard coming loose.



Applicable Vehicles: 2015MY-2016MY Genesis (DH)

Parts Information:



PART NAME	BEFORE	QTY
CLIP ASSEMBLY		1
	88399-B1000FFF	

SUBJECT:**SEAT BACKBOARD CLIP REPLACEMENT****Warranty Information:**


MODEL	OP CODE	OPERATION	OP TIME	CAUSAL PART	NATURE CODE	CAUSE CODE
Genesis (DH)	88399F00	SEAT BACKBOARD MOUNTING CLIP REPLACEMENT (1~2EA)	0.3	88399-B1000FFF	I86	ZZ6
	88399F01	SEAT BACKBOARD MOUNTING CLIP REPLACEMENT (3~4EA)	0.5	88399-B1000FFF		

Service Procedure:

1. Remove the protector (A) bottom straps located under the seat.




- 2. Place both hands at the bottom of seat backboard (B) and lift to remove from the seat assembly.




⚠ CAUTION
When removing, ensure not to damage bottom seat back retention hooks.




- 3. Lay the seat backboard on a clean workbench and inspect base clips (C).




Base clip (C) appears normal.




Base clip (C) is broken.




4. Remove broken base clip (C) and remove excess plastic to ensure base (D) is flat.






5. Tighten supplied screw (E) to half screw length in the center of the base.



6. Assemble screw (E) into the supplied new clip (F) and fully tighten to base.

NOTICE
Ensure opening (G) of clip is facing upward.



7. Reinstall seat backboard to seat assembly and reattach the protector straps.

