







Ford F53 Motorhome Chassis Engine air intake protection

Bulletin Type:	Technical Service Bulletin TSB
Bulletin #:	19-042
Job Code:	9803436
Flat Rate:	.3 hour

Publication Date:	September 2019
Make:	JAYCO, ENTEGRA
Model:	ALANTE, PRECEPT, PRECEPT PRESTIGE, EMBLEM, VISION, VISION XL,
Model Year:	2014-2020

Incident:	Removal of Protective articles on the engine air intake to air cleaner
Affected Units:	ALL 2014-2019 Class C Motorhomes built on Ford F53 Chassis
Parts Kit:	NA
Misc. Tools & Supplies:	No tools required

Instructions 19-042







FIG 1:

Open the hood of the vehicle.

FIG 2:

- Locate the air cleaner just inside the hood (arrow).
- Inspect for a <u>yellow mesh cover</u>, and a <u>blue plastic cover</u> on the intakes to the air cleaner.






FIG 3 & 4

When present, pull off the yellow mesh and blue plastic cover and discard. Close the hood.

Jayco's sole obligation under our limited warranty is to repair or replace defective materials and/or workmanship deemed our responsibility as determined by Jayco it our sole discretion. Jayco reserves the right to use new and/or remanufactured parts or materials of similar quality to complete any work, and to make parts and/or design changes as appropriate without notice to anyone. Jayco designs and/or materials changes are done without obligation to incorporate such changes in previously manufactured product. Jayco makes every reasonable effort to ensure field remedies will not adversely affect performance and/or safety of the unit. This field remedy is not intended to extend to future performance of this RV, or any of its materials, components or parts beyond the standard warranty period. The RV owner's obligation to notify Jayco, or one of its independent, authorized dealers, of a claimed defect does not modify any obligation placed on the RV owner to contact Jayco directly when attempting to pursue remedies under state or federal law.

903 South Main Street • P.O. Box 460 • Middlebury, IN 46540 • (574) 825-0608 • Fax: (574) 825-0572