

Noises from lock of valuables/stowage compartment or from gap cover between seat and center tunnel

Topic number	LI91.10-P-059389
Version	1
Design group	91.10 Front seats
Date	07-12-2014
Validity	Model series 221
Reason for change	Damage code updated
Reason for block	

Complaint:

Noises from lock of valuables/stowage compartment or from gap cover between seat and center tunnel.

Cause:

- a) Noises due to relative movement between lock and striker (picture 1).
- b) Contact surfaces between the side seat bolsters of the front seats and the center tunnel.

Attachments	
File	Description
DSCN3496.JPG	(1) Striker

Remedy:

- a) Please treat the striker with Krytox lubricant.
 - b) Please treat the leather surface of the center tunnel in the affected area with Mercedes-Benz leather care foam.
- Important note: Also perform this action when carrying out other work on the seat, even when the customer does not complain of noise at the time. Preventive performance of this work is intended to avoid follow-up repairs in the future.

Symptoms
Body / Seat / Seat noises / Cracking
Body / Seat / Seat noises / Grunting
Body / Seat / Seat noises / Knocking
Body / Seat / Seat adjustment / Stiff/sluggish
Body / Seat / Seat noises / Creaking

Parts							
Part number	ES1	ES2	Designation	Quantity	Note	EPC	Other ma-ke part
A0009893660			Krytox/lubricant	1	30ml		X
A00198659711 3			Leather care foam	1			X

Work units				
Op. no.	Operation text	Time	Damage code	Note
			68303 36	Stowage compartment tray - noises

Validity		
Vehicle	Engine	Transmission
221.022	*	*
221.028	*	*
221.054	*	*
221.056	*	*
221.070	*	*
221.071	*	*
221.077	*	*
221.080	*	*
221.084	*	*
221.086	*	*
221.087	*	*
221.122	*	*
221.128	*	*
221.154	*	*
221.156	*	*
221.170	*	*
221.171	*	*
221.176	*	*
221.177	*	*
221.179	*	*
221.180	*	*
221.184	*	*
221.186	*	*
221.187	*	*

Full model designation breakdown		
Vehicle	Engine	Transmission
221.022	642.930	722.902
221.028	629.911	722.903
221.054	272.946	722.999
221.056	272.965	722.906
221.070	273.922	722.904
221.071	273.961	722.904

221.077	156.984	722.907
221.077	156.984	722.930
221.080	642.932	722.962
221.084	273.924	722.961
221.086	273.968	722.961
221.087	272.975	722.960
221.122	642.930	722.902
221.128	629.911	722.903
221.154	272.946	722.999
221.156	272.965	722.906
221.170	273.922	722.904
221.171	273.961	722.904
221.176	275.953	722.649
221.177	156.984	722.907
221.177	156.984	722.930
221.179	275.982	722.649
221.180	642.932	722.962
221.184	273.924	722.961
221.186	273.968	722.961
221.187	272.975	722.960

Attachments

DSCN3496.JPG:

