

FT4700 Bosch Steering Gear Box Hardware Loose or Missing

Technical writer name

Yuvaraj

Manual section

7

First Level Parts (100% of 323 Buses)		
Material	Part Number	QTY
-	-	-

Nb hours Level 1	0.75 hrs
Nb hours Level 1	0.25 hrs

MQR	7621-1932
-----	-----------

No parts involved. Inspection of steering gear box assembly hardware (Replacement of missing or loose hardware).

Second level parts (15% of 323 Buses)		
Material	Part Number	QTY
WASHER SPHER 7/8" ASSEMBLY STL	N91462	3
WASHER NORD LOCK M22 STEEL ZF	N65400	3
SCREW 7/8"X4" CAP HEX STL G8	N91461	3

Disposal of parts		
Removed parts are:		When the retained check box is checked, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed,
Discarded	Retained	
Yes	-	

Client	Order	Road numbers	VIN		QTY	Lang.	Customer	Target market	Plant	Config moteur	Model	NR	R1	
New York City Transit - New York	LA73	8504	8507	L82J8J9776445	L82J8J9776476	4	E	NYCT	US	PLB	TD	40	X	
New York City Transit - New York	LB29	5531	5566	S92J9J9776687	S92J6J9776873	36	E	NYCT	US	PLB	TD	60	X	
New York City Transit - New York	LA76	8508	8633	L82J9J9776924	L82J8K9777144	125	E	NYCT	US	PLB	TD	40	X	
New York City Transit - New York	LB99	5567	5602	S92J2J9776935	S92J5K9777000	36	E	NYCT	US	PLB	TD	60	X	
New York City Transit - New York	LB78	8526	8526	L82J3K9776984	L82J3K9776984	1	E	NYCT	US	PLB	TD	40	X	
New York City Transit - New York	LC32	8634	8754	L82JXK9777145	L82J5K9777277	121	E	NYCT	US	PLB	TD	40	X	