

GPOP - Issue Review System

Part Number: 68157026A\$

Part Description: GLASS, Backlite, Sliding, Assembly

Issue Description: Before replacing this part, please call Lori Millen at (248) 379-1888.

If no response in 15 minutes, proceed with repair.

Please wrap back glass frame assembly in replacement part packing material to prevent twisting during shipping and return assembly to FCA Quality Engineering Center for analysis.

If any questions, contact Lori Millen at (248) 379-1888.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
