



# SERVICE BULLETIN

Classification: HA17-004a	Reference: NTB17-028a	Date: October 2, 2019
------------------------------	--------------------------	--------------------------

## 2014-2020 ROGUE; BLOWER MOTOR SERVICE INFORMATION

This bulletin has been amended. See **AMENDMENT HISTORY** on the last page.  
Please discard previous versions of this bulletin.

**APPLIED VEHICLE:** 2014-2020 Rogue (T32)

### SERVICE INFORMATION

When diagnosing the operation of the heating and cooling system’s blower motor, make sure there is no interference from other personal devices before replacing any parts or performing any repairs.

All personal devices (12V charger, USB charger, PC charger, etc.) must be unplugged/removed from the vehicle when diagnosing/verifying the customer issue related to blower motor operation.



**Examples of personal devices**

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

## AMENDMENT HISTORY

<b>PUBLISHED DATE</b>	<b>REFERENCE</b>	<b>DESCRIPTION</b>
March 13, 2017	NTB17-028	Original bulletin published
October 2, 2019	NTB17-028a	APPLIED VEHICLES revised