

## Implausible coolant warning message in instrument cluster

Topic number	LI20.00-P-057734
Version	3
Design group	20.00 General
Date	03-24-2014
Validity	176.052 117.352
Reason for change	Remedy and cause corrected
Reason for block	

### Complaint:

Coolant warning message in the instrument cluster although the coolant level is OK

### Note:

The warning message appears primarily when cornering

### Cause:

Sensitive warning threshold in SAM control unit (N10/1)

### Remedy:

1. Check coolant level, correct if necessary
2. Perform software update and SCN coding of SAM control unit (N10/1)

Symptoms
Power generation / Engine cooling system / Cooling system indicator lamp / Illuminates yellow
Power generation / Engine cooling system / Cooling system display / Coolant - Serviced Required

Work units				
Op. no.	Operation text	Time	Damage code	Note
			5452E F1	

Validity			
	Vehicle	Engine	Transmission
	117.352	*	*
	176.052	*	*