

FT4690R1 Hydraulic level sensor defective

Technical writer name
Devanand

Manual section 09

First Level Parts (100% of 112 vehicles)		
Material	Part Number	QTY
PLUG M-NPT-1/4	0444620	1
3 PIN WITH SHRINK BOOT	N31229-04	1
SECONDARY LOCK	N25892-03	1
PLUG, SEALING DEUTCH CONN	562288	3
TIE TEFZEL CABLE TIES	N56339	1

Nb hours Level 1 0.25 hr **MQR** 7621-1684
Nb hours Level 2 -

Disposal of parts		
Removed parts are:		When the retained check box is checked, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed,
Discarded	Retained	
X	-	

Second Level Parts		
Material	Part Number	QTY
TUBING HEATSHRINK DUAL WALL	N82227-13	60 mm

Note:
N82227-13 (TUBING HEATSHRINK DUAL WALL)
1 ea = 4 ft
60 mm/bus
6720 mm/112 buses
6 tubes for the entire campaign

Shop Supply		
Material	Part Number	QTY
LOCTITE THREAD SEALANT WHITE	N37086	2 ml
LOCTITE ACTIVATOR 7649	N8905622	0.075 oz

Note:
N37086 (LOCTITE THREAD SEALANT WHITE)
1 ea = 248.418 ml
2 ml/bus
224 ml/112 buses
1 tube for the entire campaign

N8905622 (LOCTITE ACTIVATOR 7649)
1 ea = 4.5 oz
0.075 oz/bus
8.4 oz/112 buses
2 tubes for the entire campaign

Client	Order	Road numbers		VIN		QTY	Lang.	Customer	Target market	Plant	Config moteur	Model	NR	R1	R2
Ottawa - OC transpo	LB80	4601	4609	L82J0J3751576	L82J3J3751586	9	E	-	CA	STE	TD	40	x	x	
Ottawa - OC transpo	LC16	4610	4682	L82J7K3751771	L82JXK3751912	73	E	-	CA	STE	TD	40	x	x	
Houston - Texas	LB63	2050	2050	L82K2J9776708	L82K2J9776708	1	E	Us-Prv	US	PLB	TD	40	x	x	
Houston - Texas	LB72	2051	2069	L82K6J9776887	L82K4J9776905	19	E	US-Prv	US	PLB	TD	40	x	x	
Houston - Texas	LC55	2070	2079	L82KXK9777378	L82K0K9777387	10	E	US-Prv	US	PLB	TD	40	x	x	