

2016 Golf/GTI Golf R & SportWagen



Engine	Part	Part Number	Quantity
1.8L Turbo: CXBA, CXBB	Oil Filter	06L115562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.7L (6.0qt)
	Drain Plug W/Gasket	06L103801	1
	Air Filter	5QM129620	1

Engine	Part	Part Number	Quantity
2.0L Turbo Diesel: DEJA	Oil Filter	03N115562	1
	VW 507 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.5L (5.8qt)
	Drain Plug W/Gasket	N 90813202	1
	Air Filter	5Q0129620B	1
	Fuel Filter (20K Only)	5Q0127177C	1

Engine	Part	Part Number	Quantity
2.0L Turbo GTI: CXCA, CXCB	Oil Filter	06K115562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.7L (6.0qt)
	Drain Plug W/Gasket	06L103801	1
	Air Filter	5QM129620	1

Engine	Part	Part Number	Quantity
2.0L Turbo (Golf R): CYFB	Oil Filter	06L115562	1
	VW 502 00 Use synthetic oil SAE 5W-40, SAE 5W-30	N/A	5.7L (6.0qt)
	Drain Plug W/Gasket	06L103801	1
	Air Filter	5Q0129620B	1



2016 Golf/GTI Golf R & SportWagen



2016	Engine Code		Torque Spec
Oil drain plug Torque	1.8L	CXBA, CXBB	30 Nm
	2.0L TDI	DEJA	
	2.0L	CXCA, CXCB	
	2.0L	CYFB (Golf R)	
Wheel hub bolt Torque	1.8L	CXBA, CXBB	
	2.0L TDI	DEJA	120 Nm
	2.0L	CXCA, CXCB	
	2.0L	CYFB (Golf R)	

Miscellaneous	Part	Part Number	Quantity
Miscellaneous	Pollen Filter (20K Only)	5Q0819644A	1
	Pollen Filter (20K Only) Auto	5Q0819653	1
	Front Set Wipers	5G1998002	1
	Rear Wiper Blade (Golf)*	5GM955427(A)	1
	Rear Wiper Blade (GTI)	5G6955427	1
	Rear Wiper Blade (Golf R)	5G6955427A	1
	Battery (Amp. Req. Vary)	000915105*	1

*VIN Required
Revised 11-5-2019

Resetting the service reminder display

If the service was not performed by an authorized Volkswagen dealer or an authorized Volkswagen Service Facility, the service reminder can be reset as follows:

- · Switch off the ignition.
- Press and hold the 0.0 button in the instrument cluster.
- · Switch on the ignition.
- Release the 0.0 button.
- If one of the following messages appears in the display:

Reset oil change service?

Do you really want to reset inspect. service?

• Confirm the request by pressing the $\boxed{0.0}$ button in the instrument cluster. A confirmation message appears in the display when the service reminder has been reset.

© 2019 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



2016 Golf/GTI Golf R & SportWagen



Do **not** reset the service reminder between service intervals; otherwise, incorrect information will be displayed.

The service reminder disappears after a few seconds when the engine is running or after the **OK** button on the multi-function steering wheel is pressed.