

MPD UPDATE

Powertrain



<p>AJ20P4 Coolant Pumps</p> <p>18MY onward Discovery Sport, RR Evoque, E PACE, XE, XF, F TYPE, F PACE equipped with AJ20P4</p>	
<p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - The variable coolant pump shroud is sticking causing electronic cooling fan to run at 100% duty cycle and/or illuminate the Check Engine MIL. <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - ICA parts are available through normal parts channels. - PCA parts are in the development validation stage. <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Replace coolant pumps as necessary. - There is no requirement to exclusively install parts marked with a green dot. 	
<p>KPI's</p>	
<p>Total VIN Count</p>	<p>Status</p>
	<p>Matt Priestner</p> <p>Issue Owner</p>

Solution Unavailable or project not yet accepted

Solution known, not yet delivered

Service Fix Available, Communication Published

