

MPD UPDATE

Electrical



| Intelligent Emergency Braking Warning on IPC | | 19MY – 20MY I-Pace |
|---|--------|--------------------|
| <p><u>Problem Description:</u></p> <ul style="list-style-type: none"> - Intelligent Emergency Braking warning displayed on IPC. <p><u>Current Status:</u></p> <ul style="list-style-type: none"> - Steering wheel right switch pack is cause of this warning message. - DTC B1380-87 - Steering Wheel Right Switch Pack - Missing message <p><u>Recommended Actions:</u></p> <ul style="list-style-type: none"> - Please replace the Right switch pack and report via EPQR as the part needs to be returned for analysis. | | |
| KPI's | | |
| Total VIN Count | Status | Issue Owner |
| | | NAS: Richard Conte |

Solution Unavailable or project not yet accepted

Solution known, not yet delivered

Service Fix Available, Communication Published

