

**** SOLUTION ****

Title Mack Chassis - SNM16 - 015 Updated Wiper Mechanism for One Piece Windshield;
Windshield Wipers Leaving Streaks Or Not Clearing Center Of Windshield

Mack Models

Mack Model AN - Anthem , CHU - Pinnacle, Axle back , CXU - Pinnacle, Axle front , GR - Granite
, GU - Granite , PI - Pinnacle , TD - Titan

**** SOLUTION ****

Cause In Mack Trucks SNM16 - 015 Updated Wiper Mechanism for One Piece Windshield.
Changes were made to the wiper mechanism to the body torque specification.

Solution For more information on the Mack Chassis - SNM16 - 015 Updated Wiper
Mechanism for One Piece Windshield found [here](#).

Solution visibility **Dealer distribution**

Function(s)/component(s) affected

Function affected Windshield Wiper Motor

Function Group

Function Group 3631 Windshield Wiper

Customer effect

Fluid implicated Water , Windshield Washer Fluid

Administration

Author a175606

Last modified by RU4469V

Creation date 24-05-2016 19:05

Date of last update 07-11-2019 15:11

Status Published

UNCONTROLLED COPY. Printed document is for temporary use only and should not be retained.