

GPOP - Issue Review System

Part Number: 68391566A\$

Part Description: LATCH, Folding Top

Issue Description: For a concern of a loose latch in the closed position, it is not necessary to replace the latch unless broken.

Refer to instructions in service library.

The position of the receiver attached to the vehicle header can be adjusted to change the amount of force required to latch.

~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.
~