

CAMPAIGN LAUNCH STATUS

H264 & N412 CAMPAIGNS



ONP H264 I-PACE SOFTWARE ENH.	
AFFECTED MODELS	19-20MY I-PACE (X590)
NAS VOLUME AFFECTED	4890 US 480 CAN
REPAIR	EV Software enhancement
REPAIR TIME	With IPC 1.6hrs Without IPC .5hrs
LAUNCHED	December 9 th
Notes	Software validation ongoing This campaign replaces H247

RECALL N412 EVOQUE HEADLINER	
AFFECTED MODELS	20MY EVOQUE
NAS VOLUME AFFECTED	3438 US 637 CAN
REPAIR	Temps 23 degrees Fahrenheit, the adhesive bond attaching a metal plate to the headliner of the vehicle may reduce.
REPAIR TIME	TBD
LAUNCH	Dec 5 th
Notes	Stop Sale 169 in Retailer Stock