

Subject		Market	
<b>HVAC Evaporator Cleaning Service Tips</b>		USA	
Service Category	Section		
Vehicle Interior	Heating/Air Conditioning		
Applicability			
2019-2020 Corolla Hatchback			

**APPLICABLE VEHICLES**

2019-2020	Corolla Hatchback
-----------	-------------------

**CONDITION**

On 2019-2020 model year Corolla Hatchback vehicles follow the recommendations when performing the HVAC odor maintenance service using A/C Power Foam Evaporator Cleaner & Refresher.

**RECOMMENDATIONS**

**Cover the area under the HVAC unit** – Perform this step before HVAC evaporator cleaning process is started.

1. Remove the trim components under the HVAC unit.
  - [Remove Front No.2 Console Box Insert \(RM Step #4\).](#)
2. Cover the area under the HVAC unit and its surroundings.
 

Hint: Recommend Industrial Absorbent Pads to cover.
3. Perform the HVAC odor maintenance service using Toyota Genuine A/C Refresher Kit.
4. After performing HVAC odor maintenance service, wait 30 minutes before removing absorbent material and reassembling the trim panels.

**LINK REFERENCES**

- [Link References of HVAC Evaporator Cleaning Process\(Youtube Video\)](#)