

CAMPAIGN LAUNCH STATUS

N407 & N409 UPS CAMPAIGNS



UPS N407 DRIVEABILITY IMPROVEMENTS	
AFFECTED MODELS	20MY RANGE ROVER & RANGE ROVER SPORT
NAS VOLUME AFFECTED	9525 US
REPAIR	Powertrain Control Module (PCM) and Transmission Control Module (TCM) software updates required to improve vehicle driveability
REPAIR TIME	0.3hrs
LAUNCHED	December 17 th , 2019
Notes	Update Prior to Sale

UPS N409 OBD SYSTEM READINESS	
AFFECTED MODELS	19MY RANGE ROVER SPORT
USA/CAN VOLUME AFFECTED	136 US /CAN unsold 4085 US/CAN sold cars
REPAIR	OBD system software update is required as vehicles may contain software which prevents the successful completion of OBD readiness tests
REPAIR TIME	0.3hrs
LAUNCHED	UPS December 5 th Service Action Dec 19 th
Notes	Initially an Update Prior to Sale Campaign now re-launched as a Service Action to include sold cars.