



**** SOLUTION ****

Title [Volvo Chassis - VNL Models](#) - Built With Electronic Climate Control (ECC) - HVAC: Fading Heat From The Vents, Blower Motor Working Not Properly - [Model Year 2018 and Newer](#)

Volvo Models

[Volvo Model](#) VN , VNL

**** SOLUTION ****

Cause For certain VNL model vehicles produced for model year 2018 and newer W/ Electronic Climate Control (ECC), the HVAC may start blowing cold air at random times.

Solution **DO NOT REPLACE ANY PARTS ON VEHICLES AFFECTED BY THIS ISSUE.**

To remedy this issue please program the Climate Control Module (mid 146) with Tech Tool (TT) to the latest software version.

NOTE: Trucks built with Manual Climate Control (MCC) are not effected.

Solution visibility [Dealer distribution](#)

Function(s)/component(s) affected

Function affected heating

Function Group

Function Group 871 control , 873 heating unit

Customer effect

Main customer effect temperature , efficiency/abnormal behavior

Conditions

Frequency of occurrence of problem random

Administration

Author UT0783V

Dealer ID UT0783V

Last modified by A241298

Creation date 12-09-2019 17:09

Date of last update 16-01-2020 21:01

Review date 12-11-2019 00:11

Status Published

UNCONTROLLED COPY. Printed document is for temporary use only and should not be retained.