

Latest Vehicle Concern Fixes



Noise From Dynamic Suspension	18 - 20MY Range Rover
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">A customer may report a hum/ groan type noise in the cabin when coming to a stop. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">The noise emanates from the dynamic response valve block and lasts for approximately 10 seconds. <p><u>Status:</u></p> <ul style="list-style-type: none">Revised software has been developed to address this concern and released on PATHFINDER February 12, 2020.The Workshop Manual has been updated to aid in diagnosis of the concern. Section 2: Chassis > 204-00: Suspension System - General Information > Diagnosing and Testing > Suspension System	

