



Technical Journal

TITLE:

Polestar Engineered, gold-colored tire valve stem caps

| | | | |
|--|---|--|-----------------------------------|
| REF NO: TJ 35401.1.0 | ISSUING DEPARTMENT: Technical Service | CAR MARKET: United States and Canada | |
| PARTNER: 3 US 7510 Volvo Car USA | | ISSUE DATE: 2020-01-30 | STATUS DATE: 2020-02-05 |
| FUNC GROUP: 7719 | FUNC DESC: Miscellaneous | Page 1 of 3 | |

“Right first time in Time”

Attachment

| File Name | File Size |
|-----------------|-----------|
| TJ 35401 -1.jpg | 0.0536 MB |
| TJ 35401 -2.jpg | 0.0341 MB |

Vehicle Type

| Type | Eng | Eng Desc | Sales | Body | Gear | Steer | Model Year | Plant | Chassis range | Struc Week Range |
|------|-----|----------|-------|------|------|-------|------------|-------|-----------------|------------------|
| 224 | | | P5 | | | | 2020-2020 | 70 | 0035749-0049434 | 201928-201945 |
| 225 | | | P5 | | | | 2020-2020 | 21 | 0355621-0362601 | 201928-201945 |
| 246 | | | P5 | | | | 2020-2020 | 21 | 0440441-0509901 | 201928-201945 |
| 246 | | | P5 | | | | 2020-2020 | 36 | 0441284-0511355 | 201928-201945 |
| 246 | | | PT | | | | 2020-2020 | 21 | 0465243-0508907 | 201935-201945 |

CSC Customer Symptom Codes

| Code | Description |
|------|--|
| 1F | Springs and wheels/Component springs/wheels wrong installation/missing |

Text

**DESCRIPTION:**

If the customer complains that the gold-colored tire valve stem caps are not installed, follow recommendation under Service.

During the early production of the MY 2020 Polestar Engineered vehicles, The factory may have missed to include the unique gold-colored tire valve stem caps in the vehicle (glove compartment). These caps should be installed by the dealer during the PDI.

Concerned vehicles are S60, V60 or XC60 Polestar Engineered, within structure weeks 2019w28 - 2019w45, with sales version P5 or PT.

SERVICE:

If the gold-colored tire valve stem caps were not included from factory, order one kit PN 32286322 (including 4 caps) and give them to the customer.

Warranty claim info:

No VST warranty claim accepted for a job described in this TJ. (Note: only part 32286322 may be claimed)

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 7719.

To view TJ attachment continue to next page. This TJ has two attachments.

