



66-20-01TT - No Brake Lights on the Trailer, After Trailer Module Install, DTC P1757 Present

Release date: 03/6/2020

## Condition

**ATTENTION:**

**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.  
TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

### Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Atlas, Tiguan LWB	2018-2020	All	All	All	All

### Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2058889/1	3/6/2020	66-20-01TT	Original publication.

## Technical Background

Customer complains of no brake lights on the trailer after trailer module installed. Tech may call and state fault code P175700 present after installing the trailer installation kit.

DTC	Description
P1757	System Voltage

## Service

1. Check the coding of the trailer module.
2. If coding is 01 00 00 02 02 00 00 00, change it manually in OBD address word 69 > coding.
3. Change Byte 0 to 02 and change byte 4 to 00.
4. Coding should now be 02 00 00 02 00 00 00 00.
5. Make sure the fault clears and check the trailer brake light operation with a trailer installed or a trailer test kit.

## Additional Information

© 2020 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.