



Mitsubishi Motors North America, Inc.

PARTS BULLETIN

SUBJECT:

2013 OUTLANDER SPORT FUEL GAUGE HARNESS

No: **54-US-01-13**

Date: APRIL 2013

Model:

2013 Outlander Sport AWD

PURPOSE

Due to improper part selection during the assembly process, certain 2013 Outlander Sport AWD vehicles may have been built without the installation of the fuel sending unit harness for the sub-sending unit. This may result in a false fuel tank reading. As a result, the vehicle operator may believe the vehicle still has $\frac{3}{4}$ of a gas tank of fuel when the tank is in fact empty. Reference Safety Recall Bulletin SR-13-005 for more details and remediation.

AFFECTED VEHICLES:

Certain 2013 Outlander Sport AWD vehicles built before December 12, 2012.

IMPORTANT

Affected new or used inventory vehicles must be repaired before the vehicle is delivered. Dealers must check their inventory vehicles' VINs on the Warranty Super Screen to verify whether the vehicle is involved in this recall campaign. It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by the notification under a sale or lease until the defect or non-compliance is remedied.

PARTS INFORMATION

Description	Part Number
Outlander Sport Fuel Gauge Unit Harness	8507D230

PART ORDERING AND ALLOCATION INFORMATION:

After the inspection is performed and if it is determined that a fuel sending unit harness is required, the dealer must contact their facing PDC with the corresponding VIN information to have a part allocated to your order.

There will be no initial quantity of parts sent. It is not advised for the Dealer to maintain inventory of this part.

Contact your local Zone Representative, District Parts and Service manager, or Facing PDC for questions.

