

STAR ONLINE PUBLICATION

Case Number: S2023000011

Release Date: 02/19/2020

Symptom/Vehicle Issue: Wind Noise And Or Gap At Front Door Mirror Flag

Discussion: Wind Whistle heard coming from the front of the vehicle, A-pillar or windshield frame. Inspect the mirror flag installation. The flag uses 2 metallic clips to retain it to the door. If the clips are not fully seated to the flat a gap and wind noise can result (fig 2&3). To correct, simply press the clip onto the flag until fully seated.




Fig 1 Mirror Flag

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

STAR ONLINE PUBLICATION




Fig 2

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found

STAR ONLINE PUBLICATION



Fig 3 Mirror Flag. Top Ok. Bottom clip not seated.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found