

Subject

**Pre-Delivery Service - Door Window Frame Molding
Wrap Guard Removal**

Market

USA

Service Category

Vehicle Exterior

Section

Exterior Panels/Trim

Applicability

2020 Highlander / HV

APPLICABLE VEHICLES

2020	Highlander	2020	Highlander HV
------	------------	------	---------------

CONDITION

In the interest of customer satisfaction, the adoption of wrap guard film to the Front and Rear Door, Window Frame Moldings (Black Out Moldings), was implemented on 2020 model year Highlander and Highlander HV. This film should be removed after transportation to dealerships, as part of the normal Pre-Delivery Service (PDS).



RECOMMENDATIONS

- Please be sure to use caution when removing the wrap guard during PDS (T-SB-0164-19), as you would any other locations on the vehicle.

LINK REFERENCES

This Tech Tip does not contain any link references