

Solution K18013154 Monday, April 27, 2020 7:40:08 PM CEST

** SOLUTION **

Title	Vehicles Equipped With A One-Box Emissions Aftertreatment System (EATS) - Diagrostic Trouble Codes (DTC) P2463 and P2453. US17+OBD16 (GHG17) And Newer
	Emissions, Common Model Year 2018 And Newer
Mack Models	
Mack Model	CHU - Pinnacle, Axle back, CXU - Pinnacle, Axle front, GU - Granite
Volvo Models	
Volvo Model	VNL, VNM, VNR, VAH, VHD
Emission Standard	
Emission Standard	US17, US17+OBD16, US17+OBD18
Engine family	
Engine family	11L Engine, 13L Engine, MP7, MP8
** SOLUTION **	
Cause	Chassis equipped with a US17 (GHG17) engine and one box EATS may exhibit one or both DTCs P2463 - 00 Particulate Filter Restriction - Soot Accumulation Bank 1 and P2453 - 64 Diesel Particulate Filter Pressure Sensor "A" Circuit Range /Performance with Guided Diagnostics (GD) leading to No Fault Found (NFF).
Solution	Guided Diagnostics for this code in Premium Tech Tool (PTT) verifies circuit integrity and sensor function. In addition to these tests:
	 Verify that there are no leaks around the fittings for the sensor supply tubes. Ensure that all fittings are not damaged, crossthreaded or seized. Check torque on all of the fittings and ensure none are loose.

An example of a damaged fitting can be seen below:



Solution visibility	Dealer distribution
Function(s)/compone	nt(s) affected
Function affected	Diagnostic tool, DPF
Function Group	
Function Group	254 catalytic converter; exhaust emission control equipment , 258 emissions after-treatment
Customer effect	
Main customer effect	soot, regeneration, diagnostics/methodology
Fault Codes And Erro	r Codes
OBDII Diagnostic Trouble Codes (P, U, B Format)	P2453-64, P2463-00
Conditions	
Vehicle operating mode	when driving, when stationary
Frequency of occurrence of problem	random
Administration	
Author	RU4469V
Last modified by	RU4469V
Creation date	04-10-2017 21:10
Date of last update	01-04-2020 20:04
Review date	09-12-2017 00:12
Status	Published
Average score	2.75

UNCONTROLLED COPY. Printed document is for temporary use only and should not be retained.