



## Federal Recall Information

---

**20PBC**

### Supplier

Peterbilt

---

### Description

The Tractor ABS Lamp May Not Illuminate When ABS Controller Loses Battery and/or Ignition Power. NHTSA recall number is 20V199 and Transport Canada number is 2020-148.

---

### Release Date

4/15/2020

---

### Introduction

Peterbilt Motors Company has decided that certain Model Year 2008 through 2019 vehicle Models 330, 335, 337, 340, 348, 365, 367, 384, 386, 389, 567, 579, and 587 manufactured between January 10, 2007 and March 01, 2018 fail to conform to Federal Motor Vehicle Safety Standard (FMVSS) and CMVSS No. 121 - Air Brake Systems and 136 - Electronic Stability Control Systems on Heavy Vehicles.

ABS controller loses battery and /or ignition power (e.g. the fuse blows) the ABS system becomes inoperative, in some configurations, the ABS warning lamp on the dash does not illuminate. Unknowingly operating a vehicle with an inoperative ABS system could lead to an increased risk of an accident.

---

### Resolution

This bulletin will be updated as soon as a chassis list and a repair procedure is available.

---

**It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.**

---

### Parts

No parts required, software only

---

### Attachments

[20PBC Chassis List](#)

---

Authored by: DKH

---

Access to PACCAR's Enterprise Portal is provided as a benefit of doing business with PACCAR. All applications and content accessed through this

system are confidential and proprietary and the property of PACCAR Inc and its suppliers, and must be kept strictly confidential pursuant to the contract licensing such access. Disclosure, publication, release or distribution of any material found on PACCAR systems to any person other than employees with a need to know such information is strictly prohibited. All activity on this system is monitored. If PACCAR suspects or discovers any unauthorized activity, access may be immediately terminated without prior notification. Violators may be subject to legal action.

© Copyright 2020 PACCAR Inc. All rights reserved. We welcome your [feedback](#) on this page. For technical questions or concerns about this page, please contact the [DealerNet Webmaster](#).