

FT4851 Belt Guard Beam Failure

Technical writer name / nom rédacteur technique

Manual/manuel, section

9

André Pelletier

Parts/ pièces, description	Part Number / Numero de pièce	QTY / Qté
BOLT M8X25 HEX YZ TRIV 96H 8.8	N11168	8
WASHER FLAT OVS M8 ZP DIN9021	N21101	8
WASHER LCK CURV M8 YZ TRIV 96H	N17905	8
RIVNUT M8 CSK CZ OP 1.5-4.0	N45837	4
WASHER NEOPR 1-1/4OD"X13/32ID"	2303453	2
BELT GUARD HINGE POST ASSY Yellow	N93168-02	1

Labour level 1 / main d'oeuvre niveau 1	1.5 h
---	-------

MQR	7621-1635
-----	-----------

Disposal of parts / disposition des pièces

Removed parts are / les pièces retirées sont:		When the retained check box is checked, the parts must be retained and returned in accordance with the usual warranty procedure to be reimbursed / Pour être remboursées, les pièces doivent être conservées et retournées selon le processus de garantie habituel.
Discarded / jetées	Retained/conservées	
yes		

Client	Order/Lot	Road numbers / No de véhicule		VIN / NIV		QTY / QTÉ	Lang.	Customer Group/ Groupe client	Target market / marché cible	Plant / Usine	Model / modèle	NR	R1
Houston - Texas	LB63	2050	2050	L82K2J9776708	L82K2J9776708	1	E	US-Prv	US	PLB	40	x	
Houston - Texas	LB72	2051	2069	L82K6J9776887	L82K4J9776905	19	E	US-Prv	US	PLB	40	x	
Houston Texas - Metro	LC55	2070	2079	L82KXK9777378	L82K0K9777387	10	E	US-Prv	US	PLB	40	x	