

**Classification:**

EL11-044f

**Reference:**

ITB11-066f

**Date:**

May 14, 2020

## PREMIUM NAVI/AUDIO VISUAL CONTROL UNIT DIAGNOSIS AND ORDERING

**APPLIED VEHICLES:**

2010-2013 G Sedan/Coupe/Convertible (V36)  
 2011-2013 M37/56/Hybrid (Y51/HY51)  
 2010-2013 FX35/37/50 (S51)  
 2011-2013 QX56 (Z62)  
 2010-2013 EX (J50)  
 2013 JX35 (L50)

**This bulletin is no longer applicable.**

Discard previous versions of ITB11-066.

**AMENDMENT HISTORY**

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 21, 2011	ITB11-066	Original bulletin published
December 19, 2011	ITB11-066a	SERVICE INFORMATION revised
December 21, 2011	ITB11-066b	APPLIED VEHICLES revised
May 9, 2012	ITB11-066c	APPLIED VEHICLES revised
October 31, 2012	ITB11-066d	APPLIED VEHICLES and SERVICE INFORMATION revised
July 25, 2013	ITB11-066e	SERVICE INFORMATION revised
May 14, 2020	ITB11-066f	Bulletin no longer applicable

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.